

Figure T-1 Generalized compressibility chart, $p_R \leq 1.0$. Source: E. F. Obert, *Concepts of Thermodynamics*, McGraw-Hill, New York, 1960.




Figure T-2 Generalized compressibility chart, $p_R \leq 10.0$. Source: E. F. Obert, *Concepts of Thermodynamics*, McGraw-Hill, New York, 1960.




Figure T-3 Generalized compressibility chart, $10 \leq p_R \leq 40$. Source: E. F. Obert. *Concepts of Thermodynamics*, McGraw-Hill, New York, 1960.




Figure T-4 Psychrometric chart for 1 atm (SI units). Source: Z. Zhang and M. B. Pate, "A Methodology for Implementing a Psychrometric Chart in a Computer Graphics System." *ASHRAE Transactions*, Vol. 94, Pt. 1, 1988.




Figure T-4E Psychrometric chart for 1 atm (English units). Source: Z. Zhang and M. B. Pate, “A Methodology for Implementing a Psychrometric Chart in a Computer Graphics System.” *ASHRAE Transactions*, Vol. 94, Pt. 1, 1988.