ANSWER KEY TO CHALLENGE SHEET

IGNITION SYSTEM CHALLENGE 4

Customer's Concern: I'm getting terrible gas mileage.

Customer Vehicle: Honda Civic

Possible Causes of This Challenge:

1. Leak in fuel system lines.

- 2. O₂ sensor failed.
- **3.** Leaking fuel injectors.
- **4.** Air management system not working.

Safety First Practices to Follow:

- 1. Use appropriate fuel recovery system to empty fuel tank before removing tank.
- 2. Connect vehicle exhaust system to a vent hose in a closed shop.
- 3. To prevent electrical shock, do not handle ignition components while engine is running.
- **4.** Be familiar with manufacturer's warnings of high pressure fluid.

Tools and Equipment Required:

- 1. Digital multimeter.
- **2.** PCV system tester.
- **3.** Appropriate scanner or test equipment.
- **4.** Timing light.
- 5. Hand-held vacuum pump and gauge.